


AN TAI – WRECK REMOVAL

- Project
 Technology
 Waste Management
 Operator
 Cleaning
 Well P&A
 Disconnection
 Removal & Lifting
 Other (Please Specify)

Company Details		
Company Name	Ardent	
Email		
Tel no.		

Overview (max 250 words)

Year: 1999
 Location: Malaysia
 Vessel Type: General Cargo

The An Tai, a S-14 style general cargo vessel, buckled and sank at the dock during loading operations in Port Klang, Malaysia. The vessel was cut into three sections. The stern section was pulled up by utilizing chain pullers and scrapped on site. The remaining two sections were lifted by chain pullers onto a deck barge and scrapped on site.

