


ALIA – WRECK REMOVAL

- Project
 Technology
 Waste Management
 Operator
 Cleaning
 Well P&A
 Disconnection
 Removal & Lifting
 Other (Please Specify)

Company Details		
Company Name	Ardent	
Email		
Tel no.		

Overview (max 250 words)

Year: 2000
 Location: United Arab Emirates
 Vessel Type: Rock Barge

The Alia, a jumbo deck barge that was fully Laden with large Quarry Rock, overturned in a storm in Ras al Kama, UAE. All Cargo was lost and only the bow to mid-ship of the Barge had buoyancy.

The barge was separated by means of chain cutting. The bow was refloated and scuttled in a pre-approved site. The Stern section was rigged between two barges with hydraulic pullers and recovered to surface and scuttled in a pre-approved dumping area.

